

FIG. 1A




FIG. 1B



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 2A




FIG. 2B



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 3




FIG. 4



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 5




FIG. 6



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 7




FIG. 8



APPL. NO. 09/1974,511
REPLACEMENT SHEET




FIG 9




FIG. 10



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 11






FIG. 12






FIG. 14



APPL. NO. 09/979,511
REPLACEMENT SHEET





FIG 15



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 16



APPL. NO. 09/1974511
REPLACEMENT SHEET

Numerals: Example
D Numerals: Comparative Example




FIG. 17



APPL. NO. 09/1979,511
REPLACEMENT SHEET




FIG 18





FIG. 19



APPL. NO. 09/974511
REPLACEMENT SHEET




FIG. 20



APPL. NO. 09/979,511
REPLACEMENT SHEET




FIG. 21




FIG. 22



APPL NO. 09/979,511
REPLACEMENT SHEET




FIG. 23



APPL. NO. 09/974,511
REPLACEMENT SHEET




FIG. 24




FIG. 25



APPL. NO. 09/979,511
REPLACEMENT SHEET




FIG. 26



FIG. 2A






FIG. 2B






APPL. NO. 09/974,511
 REPLY TO OFFICE ACTION OF NOV. 25, 2003
 ANNOTATED SHEET SHOWING CHANGES

15/24

FIG. 17






APPL. NO. 09/974,511
REPLY TO OFFICE ACTION OF NOV. 25, 2003
ANNOTATED SHEET SHOWING CHANGES

18/24

FIG. 20





replace
with
"PNEUMATIC"

FIG. 21






FIG. 24

replace
with
"PNEUMATIC"

